RECEIVED

By Recall Management Division at 1:13 pm, Jun 20, 2014





Ms. Nancy Lewis
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
1200 New Jersey Avenue SE, Room W45-306
Washington, DC 20590

June 20, 2014

Re.: REVISED Notification of a Special Service Program (SSP) for 2003-2007 Model Year (MY)
Mazda6, 2004-2008 MY RX-8, 2006-2007 MY Mazdaspeed6 and 2004 MY MPV vehicles with Air
bag Inflators supplied by Takata Corporation and TK Holdings, Inc.

Dear Ms. Lewis:

Mazda Motor Corporation (Mazda) is aware of several field reports regarding airbag deployments for a variety of vehicle brands equipped with air bag inflators supplied by Takata Corporation and TK Holdings, Inc. There is insufficient information at this time to determine the cause of these incidents or if they are related to a safety defect, but Mazda is working with the supplier and NHTSA to investigate these incidents as guickly as possible.

Yesterday, Mazda notified you that we plan to implement a Special Service Program (SSP) in limited regions of the United States in order to minimize the possibility of additional incidents occurring in the field and to support the expedited collection of parts for analysis. The areas of the United States that will be included by Mazda are Florida, Hawaii, and Puerto Rico. Mazda North American Operations (MNAO), on behalf of Mazda Motor Corporation of Hiroshima, Japan (Mazda), submits the following information concerning this voluntary action.

I . Manufacturer's Name:

Mazda Motor Corporation with Designated Agent:

David Robertson, Group Manager Environmental, Safety and Powertrain Engineering Mazda North American Operations 46976 Magellan Drive Wixom, MI 48393

II . Potentially Affected Vehicles:

Mazda has determined that the subject vehicles of the SSP are certain model years of the Mazda6, Mazdaspeed6, RX-8, and MPV which are equipped with similar types of airbag inflators. Specifically the vehicles are identified as:

*2003-2007 MY Mazda6 built from October 4, 2002 through July 31, 2007. Plant information: Auto Alliance International, Inc. Flat Rock, Michigan. Vin Range: 1YVFP8***35 M00415 - M57051 , 1YVHP8***35 M00460 - M53091 , 1YVFP8***45 M07463 - M99253 , 1YVHP8***45 M07480 - M99243 , 1YVFP8***55 M00087 - M76942 , 1YVHP8***55 M00054 - M77480 , 1YVFP8***65 M00408 - M71141 , 1YVHP8***65 M00086 - M71444 , 1YVHP8***75 M00016 - M61951

- 2004-2008 MY RX-8 built from April 23, 2003 through July 26, 2007.
 Plant information: Hiroshima plant of Mazda Motor Corporation, Japan
 Vin Range: JM1FE1***40 100063 140879 , JM1FE1***50 140895 161156 ,
 JM1FE1***60 200013 207444 , JM1FE1***70 207473 214011
 JM1FE1***80 214012 214263
- 2006-2007 MY Mazdaspeed6 built from August 25, 2005 through June 28, 2007.
 Plant information: Hofu plant of Mazda Motor Corporation, Japan
 Vin Range: JM1GG1***61 100133 108016, JM1GG1***71 108061 110732
- 2004 MY MPV built from August 21, 2003 through July 28, 2004.
 Plant information: Hiroshima plant of Mazda Motor Corporation, Japan
 Vin Range: JM3LW2***40 500024 531700 , JM3LW2***50 531899 556188 ,
 JM3LW2***60 556764 571747

Basis of determination of the recall population:

The vehicle population was based on manufacturing records of Mazda.

Affected Component:

Driver and/or Passenger side frontal air bag unit

(For Mazda6)

Manufacturer: TK Holdings Inc.

Address:

888 16th Street, NW, Suite 800 Washington, DC 20006

Country of Origin:

Mexico

(For RX-8,Mazdaspeed6,and MPV) Manufacturer: Takata Corporation

Address:

12-31 Akasaka 2-chome, Minato-ku, Tokyo, 107-8508, Japan

Country of Origin:

Japan

III. Estimated Population of Vehicles Potentially Affected

The estimated population is approximately 34,600 vehicles that were originally sold or are currently registered in Florida, Hawaii, and Puerto Rico. Mazda vehicles have not been sold or registered in the U.S. Virgin Islands.

IV. Description of the concern:

On the vehicles identified above the air bag may not deploy properly in the event of an accident.

V. Chronology of Events:

- On June 11, 2014 NHTSA opened the Preliminary Evaluation (PE14-016) with regard to the excessive deployment of both driver and passenger side frontal air bags manufactured by Takata.
- On June 13, 2014 NHTSA coordinated a conference call with several OEMs, including Mazda, to discuss a limited voluntary recall action with parts collection and analysis in order to quickly understand this concern more fully and identify the root cause.
- On June 19, 2014 Mazda has decided to conduct an SSP, which will include owner notification in the effected regions, on the vehicles, 2003-2007MY Mazda6, 2004 2008MY RX8, 2006-2007MY Mazdaspeed6 and 2004MY MPV.

V. Service Program

Owners of record will be notified of this issue and instructed to take their vehicles to a Mazda dealer to replace the air bag inflator with a new one. The work will be performed by Mazda authorized dealers, free of charge to the vehicle owners.

The expected dates for mailing owner notification letters and providing notification to dealers are currently undecided. It will depend on the availability of replacement parts from the supplier. Mazda may implement a phased approach of notifying customers in accordance with the expected supply of repair parts.

VI. Copy of notification letters:

A copy of the "owner notification letter" will be submitted when it becomes available. Mazda does not plan to provide for reimbursement for repairs paid by customers prior to this action, since the concern is only present in the event of an airbaq deployment.

VII. The Manufacturer's Campaign Number:

Mazda has assigned SSP number SSP96 to this action.

1 A VV

Sincerely yours

David Robertson, Group Manager, Environmental, Safety & Powertrain Engineering

Mazda North American Operations